



1077 GORGE BOULEVARD AKRON, OH 44310 P.O. BOX 88 AKRON, OH 44309-0088 (216) 384-8184



July 23, 1991

Illinois EPA
Division of Land Pollution Control
Leaking UST Section
2200 Churchill Road
P. O. Box 19276
Springfield, Illinois 62794-9276
Re: Incident 911816
Roadway Express, Inc.
Chicago, Illinois

As requested in your Corrective Action Response and Report Requirements (CARRR), the following information is provided to fulfill the 20-day reporting requirement. This information is provided in the same numerical sequence used in the CARRR request:

- 1. The released material was diesel fuel. The exact volume released is estimated to be between 100 and 200 gallons.
- 2. Refer to the enclosed map for UST locations, etc.
- 3. Refer to enclosed drawings for monitor well locations.
- 4. Land use in the area is primarily agricultural except for two large truck terminals which are connected to city-supplied water and sewer.
- 5. No analytical results are available.
- No photographs have been taken.

## Additional items:

- 1. A small crack in the top of the tank has been repaired.
- 2. All free product that accumulates in the monitor well is bailed out.
- 3. The extent of contamination has tentatively been identified by soil borings. It does not appear that any subsurface structures have been impacted.



- 4. A site investigation (soil borings) has been undertaken to assess subsurface conditions. Subsequent to a review of available data, a corrective action plan will be prepared.
- 5. Soil borings advanced in the tank cavity indicate a pea gravel backfill material with native soils consisting primarily of interbedded sands, silts and clays. No groundwater was encountered to a depth of 22 feet. Soil samples were field screened utilizing a P.I.D. meter.
- 6. See item 5 above.

If you have any additional questions please contact me at 216/258-2443.

Very truly yours,


Roadway Services, Inc. for Roadway Express, Inc.

Grant B. Wilk

Environmental Geologist

jmc/gbw5
Enclosures

## Complete this form. **Contingency Plan Leaking Underground Storage Tank Problems** Incident # Site Name Address Site Phone Person representing the site with authority to approve remediation expenditures in an emergency Kandy Aver Phone \_ After-hours Phone Contractor Hired for Tank Removal \_\_\_ After-hours Phone \_\_\_\_ Contractor Available for Emergency Response Heritaire Phone 708 139 1150 After-hours Phone In case of Additional Petroleum Product spillage or discovery of products or vapors in the Sewers, Streams, and/or Buildings IMMEDIATELY Notify all the Following: Local Fire Department \_\_\_\_\_\_ Phone \_\_\_\_\_\_Phone 758 1321 1331 Local Police Department \_\_\_ Phone 3330 Sewer Authority \_\_\_\_\_ Phone \_\_\_\_ After-Hours Phone Illinois Emergency Services and Disaster Agency and ask for the IEPA Duty Officer Phone 800/782-7860 Confirm that the emergency contractor is available and willing to respond to this site. Then post the original in a prominent place for your employees and send the carbon to: IEPA-ERU #29 2200 Churchill Road Post Office Box 19276 Springfield, Illinois 62794-9276 Illinois Environmental Protection Agency — Emergency Response IEPA-ERU Phone 217/782-3637





1968

FIGURE 3



SITE LOCATION MAP

CHICAGO HEIGHTS

